BIOS™ Professional

Digital Receiving Scale
Model: 603SC

Model	603SC
Capacity	100 kg/220 lb
Minimum Weight	0.3 kg/0.66 lb
Resolution	0.1 lb/0.05 kg/2 oz or 0.2 lb/0.1 kg/4 oz
Weighing Units	Pounds (lb), kilograms (kg), pounds &ounces (lb/oz)
Display	White Backlit LCD
Platform Dimension	11.7" x 11.22" x 1.22"/29.8 x 28.5 x 3.1 cm
Power	4 x AA batteries (included) & AC-Adapter (included)

Thank you for purchasing the BIOS Professional™ Digital Receiving Scale. To ensure proper operation and to maintain the lifespan and the utmost accuracy of the scale, please read this manual carefully and in its entirety before use.

For best results, only operate this scale on a flat and stable surface.

Battery Install

1. Turn over the remote and slide off the battery cover.
2. Insert 4 x AA batteries according to their correct polarity.

NOTE: Inserting the batteries incorrectly may cause harm to the scale.

3. Next, slide the battery cover back on. Now your scale is ready for use.
4. Replace batteries when the scale display is blank or shows "LO" on the screen when powered on.

Operation

1. Press the **"ON/OFF"** button to turn the scale on.
2. Wait until the display shows "0.0" (zero) before placing any weight on the scale.
3. Carefully place the item(s) to be weighed onto the weighing platform.
4. After a few seconds, the weight should stabilize and you can now get your weight reading from the LCD remote display.
5. Press the **"UNIT"** button to switch between weighing units (lb, kg, lb/oz).

Tare Weighing

The Tare button resets the display to zero when weight is on the scale, allowing you to subtract the weight of a container.

1. Place the container you wish to use on the platform.
2. When the readout stabilizes press the **"TARE"** button once.
3. The remote display will reset to zero allowing you to now add items to the container and obtain the weight of just the contents (net weight) not including the container.

Calibration

1. Place the scale on a smooth, flat surface.
2. Press the **"ON/OFF"** button and wait until it shows 0.00 kg on the display. If it's not on kg, press the **"UNIT"** button until it is.
3. Press and hold the **"UNIT"** button for 6 seconds. The display will show 100kg and 10kg, or 100kg and 20kg, or 100kg and 50kg.
4. Press the **"TARE"** button to switch calibrated weight between 10kg, 20kg, 50kg. You can choose calibrated weight 50kg, press "**UNIT**" button, you will see CAL on the screen and then 50 kg will start to flash.
5. Next, place 50 kg of weight on the scale. The weight will stop flashing.

NOTE: If you put less than or more than 50 kg on the scale the 50 kg will continue to flash until you put the correct amount on the scale.

6. Your scale is now successfully calibrated.

Proper Care Instructions

Do not expose scale to moisture
Do not drop or mistreat the scale
Do not overload the scale. This will permanently damage it.
Do not leave weight on the scale when not in use.
To clean, wipe down with a damp cloth. **Do not** submerge scale in water.

One Year Warranty

This product has a 1 year warranty to be free of manufacturing defects in materials and workmanship under normal applications for the original owner. If this product becomes inoperable due to defect and requires correction, return the product with all component pieces and proof of purchase to the address listed below. This warranty does not cover any shipping/transport costs. This warranty does not apply if the product is subject to misuse, neglect, rough handling or damage.
Ship the unit prepaid and insured (at owners option) to:

THERMOR LTD.
Returns Department
16975 Leslie Street
Newmarket, ON L3Y 9A1
www.biosmedical.com
Email: support@biosmedical.com

MANUFACTURED BY/FABRIQUÉ PAR :
THERMOR LTD.
16975 LESLIE STREET
NEWMARKET, ON L3Y 9A1
MADE IN CHINA/FABRIQUÉ EN CHINE
WWW.BIOSPROFESSIONAL.COM
100% Canadian Owned & Operated
Propriétaire-exploitant canadien à 100 %